Hi **≫**,

I have spoken to our Ops colleagues at FLL and have answers to your follow-up questions.

1) Could you confirm that: 4017 was the inwards traffic, from Lawley Street, the return train, was 4M79, (2253 from Millbrook/2253 Maritime).

4017 (inward traffic from Lawley Street) formed 4E01 (ETD 0215).

2) When was this? (you say 'recently' but could you specify for us). How many months did it last?

4017 was moved to Maritime in February 2014 but resulting terminal performance issues resulted in the service returning to Millbrook after approximately 2 weeks. These performance issues are outlined in page 6 of our response.

3) What happened to the flow after you decided it did not work operationally [at Maritime]?

The flow returned to Millbrook - see track occupation chart in Appendix 5.

If you need any further information on any of this please let me know.

Regards,

Rail Strategy Manager
Freightliner Group Limited

Tel: ⊁ Mobile: ⊁ Email: ⊁

Web: www.freightliner.co.uk

Freightliner® is a registered trademark

Please consider the environment before printing this email