## **PROSECUTION**

**Case Number** 4005322

**Summary** Deficient track maintenance caused the Swansea-

Paddington High Speed Train (which was carrying approximately 450 passengers and traveling close to the permitted line speed of 125mph) to derail while passing over a points crossover. Fortunately the train remained upright and there were no injuries amongst

the passengers.

The incident was caused by part of a fishplate (used to join lengths of track) which had broken, become detached from the rail and lodged in the crossover. Investigation showed numerous other deficiencies in

the track which had contributed to the failure.

Company Network Rail Infrastructure Ltd

40 Melton St London NW1E 2EE

Breaches involved Health and Safety at Work etc Act 1974 Section 3(1)

Date(s) of offence 24 November 2002

**Plea** Guilty

**Result** Gulity and fined on 12 September 2006 at the Old

Bailey.

**Penalty** £200,000

**Costs** £19,714

Location of offence

Address Southall East Junction

**ORR** details

ORR Area Team Western

**ORR Directorate** Railway Inspectorate