

## PROSECUTION

<b>Case number</b>	4074310
<b>Summary</b>	The residual current device (RCD) was defective and had been out of action for at least 20 months, despite several maintenance visits identifying the fault and the need for action. This resulted in two Channel Tunnel Rail Link workers who were carrying out repairs receiving an electric shock when they touched the perimeter fence. There was also a danger to members of the public who walking next to the line could have also received an electric shock had they touched the fence..
<b>Company</b>	Network Rail Infrastructure
<b>Breaches involved</b>	Electricity at Work Regulations 1989, Regulation 4 (2)
<b>Date(s) of offence</b>	23 April 2005
<b>Plea</b>	Guilty
<b>Result</b>	Guilty and fined at Blackfriars Crown Court on 19 September 2008
<b>Penalty</b>	£120,000
<b>Costs</b>	£ 10,000.00

### Location of offence

<b>Address</b>	Belle Isle Nr Kings Cross
----------------	------------------------------

### ORR details

<b>ORR Area Team</b>	Kent & Anglia
<b>ORR Directorate</b>	Railway Inspectorate