## PROSECUTION

Summary	incidents while ma two Impr Notice re 650V ele were cat exposed were bro did not n failed to	mber 2013, following an investigation into two s where rail workers suffered electric shocks aintaining signalling equipment, ORR served rovement Notices on Network Rail. The first equired Network Rail to inspect thousands of ectrical cabinets. This identified that there binets to which members of the public were . The second Notice required that these bught up to a safe standard. The company nake sufficient progress with this work and comply with the Notice by the due date, DRR to launch a prosecution.	
Company	Network	Rail Infrastructure Limited	
Breaches invo		Health and Safety at Work etc Act 1974 Section 33(1)(g)	
Date(s) of offe	ence 22 <sup>nd</sup> Feb	22 <sup>nd</sup> February 2014	
Plea	Guilty		
Result	Guilty		
Court	Blackfria	rs Crown Court,	
Sentencing da	ate 4 <sup>th</sup> Augu	4 <sup>th</sup> August 2016	
Penalty	£70,000	fine	
Costs	£94,966.	.18	
	Location of o Address ORR details ORR Team ORR Directorat	1 Eversholt Street, London LNW(N)	